



750/760 Feeder Management Relay (Basic Option) Firmware release notes

GE Publication Number: GER-4040

Copyright © 2005 GE Multilin.

Overview

Summary

- Affected products: 750/760 Feeder Management Relay (Basic Option)
- Date of release: January 10, 2005
- Firmware revision: 5.02
- Hardware revision: I
- Boot code revision: 3.20

Release summary

GE Multilin has released a new version of the 760 Feeder Management Relay with an updated autoreclosure algorithm. With this new version, the autoreclose function will lockout when any of the elements is in "operate" status (not in "pickup" status) after a manual close.

GE Multilin technical support

GE Multilin contact information and call center for product support is shown below:

GE Multilin
215 Anderson Avenue
Markham, Ontario
Canada L6E 1B3

Telephone: 905-294-6222 or 1-800-547-8629 (North America), +34 94 485 88 00 (Europe)
Fax: 905-201-2098 (North America), +34 94 485 88 45 (Europe)

E-mail: multilin.tech@indsys.ge.com
Home Page: <http://www.GEindustrial.com/multilin>

Release details

Modified features

Autoreclose: new firmware version

In previous revisions of the 760 Feeder Management Relay, the Autoreclose function used to lockout when any of the elements was in pickup status after a manual close.

The new version has updated the algorithm so the Autoreclose function will lockout when any of the elements is in operate status after a manual close.

Instruction manual changes

Updated publication number

The publication number for version 5.02 of the 750/760 relay has been updated to GEK-106293C.

Changes to the autoreclose section

The description in the Autoreclose section has been updated to reflect changes to the autoreclose algorithm.