

# Multinet Setup Software

## Revision 3.00 Release Notes

GE Publication Number: GER-4394

Copyright © 2010 GE Multilin

### Overview

---

## Summary

GE Multilin issues the Multinet v3.00 setup software release that introduces the following features to the Multinet, Multinet 4 & Multinet 1000 Router .

- **Added Multinet 1000 Router support to the Multinet family setup software**
- **The software replaces the existing Mutinet\_ 100 Multinet 4 setup software & Multinet 2.02 Multinet setup software**
- **Released Nov 26<sup>th</sup>, 2010**

### Release details

---

In the following enhancement descriptions, a revision category letter is placed to the left of the description. Refer to the Appendix at the end of this document for a description of the categories displayed.

## Enhancements

E

### **Added the Support for Multinet-1000 Router**

This software suite has added the support for the newly launched Multinet-1000 Router.

## Appendix

### Change categories

This document uses the following categories to classify the changes.

**Table 1: Revision categories**

Code	Category	Comments
N	New feature	A separate feature added to the relay. Changes to existing features even if they significantly expand the functionality are not in this category
G	Change	A neutral change that does not bring any new value and is not correcting any known problem
E	Enhancement	Modification of an existing feature bringing extra value to the application
D	Changed, incomplete or false faceplate indications	Changes to, or problems with text messages, LEDs and user pushbuttons
R	Changed, incomplete or false relay records	Changes to, or problems with relay records (oscillography, demand, fault reports, etc.)
C	Protocols and communications	Changes to, or problems with protocols or communication features
M	Metering	Metering out of specification or other metering problems
P	Protection out of specification	Protection operates correctly but does not meet published specifications (example: delayed trip)
U	Unavailability of protection	Protection not available in a self-demonstrating way so that corrective actions could be taken immediately
H	Hidden failure to trip	Protection may not operate when it should
F	False trip	Protection may operate when it should not
B	Unexpected restart	Relay restarts unexpectedly

The revision category letter is placed to the left of the change description.

### GE Multilin technical support

GE Multilin contact information and call center for product support is shown below:

GE Multilin  
215 Anderson Avenue  
Markham, Ontario  
Canada L6E 1B3

Telephone: 905-294-6222 or 1-800-547-8629 (North America), +34 94 485 88 00 (Europe)

Fax: 905-201-2098 (North America), +34 94 485 88 45 (Europe)

E-mail: [multilin.tech@ge.com](mailto:multilin.tech@ge.com)

Home Page: <http://www.GEmultilin.com>