GE
Grid Solutions

EnerVista Launchpad v5.05
Release Notes

Overview

Summary

GE has released EnerVista Launchpad v5.05 which introduces the following features and enhancements:

- o Quality Updates

Release Date: February 16, 2021

Release Details
Quality Updates

In the following descriptions, a revision category letter is placed to the left of the description. Refer to the Appendix at the end of this document for a description of the categories.

G   Update help content containing Adobe Flash movies

As Adobe Flash support has been discontinued, the LaunchPad help content has been revised to contain written instructions.

System Requirements

COMPONENT	REQUIREMENT
Supported Operating Systems	• Windows® 7 – 32 or 64 bit
	• Windows® 10 – 32 or 64 bit
Other	• Adobe Reader (for viewing reports in PDF format)

Change categories

This document uses the following categories to classify the changes.

Table 1: Revision Categories

Code	Category	Comments
N	New feature	A separate feature added to the relay. Changes to existing features even if they significantly expand the functionality are not in this category
G	Change	A neutral change that does not bring any new value and is not correcting any known problem
E	Enhancement	Modification of an existing feature bringing extra value to the application
C	Protocols and communications	Changes to, or problems with protocols or communication features

The revision category letter is placed to the left of the change description.

For Further Assistance

For product support, contact the information and call center as follows:

GE Grid Solutions
650 Markland Street
Markham, Ontario
Canada L6C 0M1

Worldwide telephone: +1 905 927 7070
Europe/Middle East/Africa telephone: +34 94 485 88 54
North America toll-free: 1 800 547 8629
Fax: +1 905 927 5098
Worldwide e-mail: multilin.tech@ge.com
Europe e-mail: multilin.tech.euro@ge.com
Website:http://www.gegridsolutions.com/multilin/