2.01 TO 2.10 (August 3, 1999)

1. Support for version 2.10 device firmware
2. Added Modbus/TCP support. Configuration can be accessed through the Communication / Computer menu
3. Added Site Setup to the modem dialog box. This allows users to add names to identify unique slave addresses at each site.
4. Added the ability to optionally hide the prompt for confirmation messages after storing setpoints. This option can be accessed through "Confirm Store Operations" on the Menu bar.
5. Modem Redial Timeout maximum range changed to 120 seconds from 60 seconds.
6. Changed the descriptive name for Actual Value / Metering / Percentage Slip to *Motor Speed*.