



GE VERNOVA

GRID Solutions

Hardware Options N, P, Q, & R for P40 Agile End-of-Manufacturing/Supply Notice

Excerpt from Publication Number: GER-4938

Issued: 12th December 2022

Revision Dates:

- 18th December 2023 (Excerpt from End-of-Manufacturing Notice GER-4956)
- 2nd December 2025 (Rebranding Revisions)

Copyright © 2025 GE Vernova

Background

GE Vernova Grid Solutions is committed to customer care and the support of our offerings. As part of this commitment, we strive to design high quality offerings, provide knowledge-based support, and to communicate the availability of new features or offerings as well as the pending discontinuation of manufacturing for older offerings or design variants.

On 12th December 2022, the discontinuation of the manufacturing and supply of Hardware Options N, P, Q, & R for P40 Agile was announced.

On 18th December 2023, the alternatives were revised from P40 Agile Hardware Options A, B, or C to Multilin Agile Hardware Options A, B, or C.

On 2nd December 2025, this notice was revised in accordance with GE Vernova rebranding guidelines.

Last-Time Buy Window

Please plan the purchase of any additional quantities or spares that you need. Orders should be placed prior to the last order date shown. Orders will be fulfilled based upon availability and shipments typically occur within three months of last order date. Requests for delayed shipments must be agreed with our factories prior to order acceptance.

OFFERING	LAST ORDER DATE	ALTERNATIVE
<p>P40 Agile Hardware Options N, P, Q, & R</p> <p>Options: N – EIA RS485/IRIG-B (Demodulated) & Dual Copper Ethernet - 2x RJ45 Copper (Dual IP) P – EIA RS485/IRIG-B (Demodulated) & Dual Redundant Fiber Ethernet - 2x Multimode Fiber (Dual IP) Q – EIA RS485, EIA RS485/IRIG-B (Demodulated) & Dual Copper Ethernet - 2x RJ45 Copper (Dual IP) R – EIA RS584, EIA RS485/IRIG-B (Demodulated) & Dual Redundant Fiber Ethernet - 2x Multimode Fiber (Dual IP)</p> <p>Order Cdes: P14DxxNxxxxxxxx P14NxxNxxxxxxxx P94VxxNxxxxxxxx P14DxxPxxxxxxxx P14NxxPxxxxxxxx P94VxxPxxxxxxxx P14DxxQxxxxxxxx P14NxxQxxxxxxxx P94VxxQxxxxxxxx P14DxxRxxxxxxxx P14NxxRxxxxxxxx P94VxxRxxxxxxxx</p>	<p>1st November 2023</p>	<p>Multilin Agile Hardware Options A, B, or C</p> <p>Options: A – 2x EIA RS485 Serial, 2x RJ45 Ethernet (Configurable PRP/HSR/LLA) & 1x RJ45 B – 2x EIA RS485 Serial, 2x Fiber Ethernet (Configurable PRP/HSR/LLA) & 1x RJ45 C – 2x EIA RS485 Serial, 2x Fiber Ethernet (Configurable PRP/HSR/LLA) & 1x Fiber</p> <p>Order codes: P14DxxAxxxxxxxxE P14NxxAxxxxxxxxE P94VxxAxxxxxxxxE P14DxxBxxxxxxxxE P14NxxBxxxxxxxxE P94VxxBxxxxxxxxE P14DxxCxxxxxxxxE P14NxxCxxxxxxxxE P94VxxCxxxxxxxxE</p>
<p>P40 Agile Hardware Options N, P, Q, & R</p> <p>Options: N - EIA RS485/IRIG-B (Demodulated) & Dual Copper Ethernet - 2x RJ45 Copper (Dual IP) P - EIA RS485/IRIG-B (Demodulated) & Dual Redundant Fiber Ethernet - 2x Multimode Fiber (Dual IP) Q – EIA RS485, EIA RS485/IRIG-B (Demodulated) & Dual Copper Ethernet - 2x RJ45 Copper (Dual IP) R – EIA RS584, EIA RS485/IRIG-B (Demodulated) & Dual Redundant Fiber Ethernet - 2x Multimode Fiber (Dual IP)</p> <p>Order codes: P24DxxNxxxxxxxx P24NxxNxxxxxxxx P24DxxPxxxxxxxx P24NxxPxxxxxxxx P24DxxQxxxxxxxx P24NxxQxxxxxxxx P24DxxRxxxxxxxx P24NxxRxxxxxxxx</p>	<p>1st November 2023</p>	<p>P40 Agile Hardware Options E, F, L, or M</p> <p>Options: E – EIA RS485/IRIG-B (Demodulated) & Dual Redundant Copper Ethernet - 2x RJ45 Copper (Setting Configurable As PRP Or HSR) F - EIA RS485/IRIG-B (Demodulated) & Dual Redundant Fiber Ethernet - 2x Multimode Fiber (Setting Configurable As PRP Or HSR) L – EIA RS485, EIA RS485/IRIG-B (Demodulated) & Dual Redundant Copper Ethernet - 2x RJ45 Copper (Setting Configurable As PRP Or HSR) M – EIA RS584, EIA RS485/IRIG-B (Demodulated) & Dual Redundant Fiber Ethernet - 2x Multimode Fiber (Setting Configurable As PRP Or HSR)</p> <p>Order codes: P24DxxExxxxxxxxx P24NxxExxxxxxxxx P24DxxFxxxxxxxx P24NxxFxxxxxxxx P24DxxLxxxxxxxx P24NxxLxxxxxxxx P24DxxMxxxxxxxx P24NxxMxxxxxxxx</p>

End-of-Manufacturing/Supply Notice

Support

GE Vernova's warranty provision is unaffected by this End-of-Manufacturing/Supply Notification. After the published last order date elapses, a repair service follows for items no longer under warranty subject to availability that includes repairing failed components or modules, but not to providing advanced replacements or a new product or module as a replacement or spare.

Customers should contact us if they need further information concerning the level of service that is provided on a per offering basis.

For Additional Information

If we can provide assistance with migration to new offerings, please contact us for help. Advice and assistance are also available via: <https://www.gevernova.com/grid-solutions/contact.htm?loc=3> or <https://www.gevernova.com/grid-solutions/automation/protection-control-metering>.